Technic	al Bulletin	Model 6 Cyl.	Group 3
Subject		Part Identifier 3702	Numbe 9504
	onic Transmission Fluid Level	5702	5304
ATTENTION: Ser	vice Manager / Service Technician		
Models Affected:	911 Carrera 2 1990-1994		
Concern:	The Porsche Workshop Manual 91 page 38-101 of supplement XXII, ir should read " below the 80°C MAX be entered in a future supplement. Workshop Manual on the above me	the second paragraph u mark present)". This info Please write this change	nder "Note" ormation will
	star pr articular Propo star Star Star Star Star Star Star Star S	ng the A17 tube level method buckness the distributions the distri	
	below the 80°C MHX mark present).	In English and And The	
		Gerger, J. XX. 1944	
hat may occur on some vehicles, or to n these bulletins. Use of tools and proce- he equipment, tools, safety instructions vehicle will have that condition. See your	Technical Bulletins are intended for use by professional technicians, not a "Do-it-you provide information that could assist in the proper service of a vehicle. Specia dures other than those recommended in these bulletins may be detrimental to the and know-how to do a job properly and safely. If a condition is described, do r Porsche Dealer for information on whether your vehicle may benefit from the infor orsche dealer to verify correct part numbers.	I tools may be required to perform cer safe operation of your vehicle. Properly ot assume that the bulletin applies to pormation. Part numbers listed in these to	tain operations ident trained technicians h our vehicle, or that
Dealership Serv	ice manager Shop foreman Service tech	nician	
Routing Asst	. manager Warranty admin Service tech		
	®, Tiptronic [®] , Variocam [®] and the Porsche Crest are registered trademarks of Dr. Ing	h.c.F. Porsche AG and its affiliate, Porsc	he Cars North Americ
©1995 Porsche Cars North America, Inc. All rights reserved. Cannot be reproduced without written permission. Service & Parts Publications.	SERVI		Page 1 of 1 ine 20, 1995