

Technical Bulletin

Model
911 Carrera 4
911/Turbo

Group
1

Subject: Modified Oil Return Tube
Sealing Ring

Part Identifier
1545

Number
8908

The material of the oil return tube seal has been changed.

From production date: November 17, 1988

Engine Number:

64 K 03054 - Carrera

68 K 00659 - Turbo

62 K 00204 - Carrera 4.

New seal ring: PN 999 707 112 40

New oil tube service kit: PN 930 107 040 01

Only the new seal, green color, should be installed when repairing engines. When using oil tube service kits or engine gasket kits containing red colored seals, obtain and use green seals.

DOTSUCHE CARS NORTH AMERICA, INC.

Important Notice

PCNA Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers.

© 1989 Porsche Cars North America, Inc.



SERVICE

Page 1 of 1
April 7, 1989