

# **Technical Information**

#### **Piston Spray Jets**

911 (964 & 993) 1/97 1013

Binder - Service Technical Bulletins

Vehicle Type:	911 Carrera (964 and 993)						
Model Year:	As of 1989 (K)						
Concern:	Correct application of piston spray jets						
Information:	As of Model Year 1989, piston spray je are installed in the engine case for eac following information will assist in selec for a particular engine type. The spray version or long version in standard dian diameter.						
Application:	Normally Aspirated Engines		Figure 1				
	Model Year 1989 to 1994 Engine Types M64.01/02/03/04 Cylinders #1 to #6 short spray jets						
	Model Year 1995 Engine Types M64.05/06/07/08 Cylinders #1 to #6 short spray jets						
	Model Year 1995Engine Types M64.05/06/07/08/20As of start of production:As of February 1995 production:cylinders #1 to #6 short spray jetscylinders #1, #2, #3, #5 and #6 short spray jetscylinder #4 long spray jet						
	Model Year 1996 Engine Types M64.20/21/22/23/24 As of start of production: As of September 1995 production:	cylinders #1 to #6 short spray jets cylinders #1, #2, #3, #5 and #6 short spray jets cylinder #4 long spray jet					
	Model Year 1997 Engine Types M64.21/22/23/24 Cylinders cylinders #1, #2, #3, #5 and Cylinder #4 long spray jet	l #6 short spray jets					



### 911 (964 & 993) 1013 **1/97**

## **Technical Information**

#### Application: (cont'd) Turbo Engines

Model Year 1991 and 1992 Engine Type M30.69 Cylinders #1 to #6 short spray jets

Model Year 1994 Engine Type M64.50 Cylinders #1 to #6 short spray jets

As of Model Year 1996 Engine Type M64.60 Cylinders #1 to #6 long spray jets




Figure 2

- Repairs: For installation of a "Long Spray Jet" the depth of the bore for the spray jet must be 33mm. If the depth of the bore is less than 33mm a short spray jet must be installed. The spray jet bore is measured to the first shoulder in the bore (Figure 2). **The bore must not be reworked**.
- Parts:964 101 905 10<br/>964 101 020 00<br/>993 101 018 51Universal engine case equipped with 6 Long Spray Jets.<br/>Short Spray Jet (length 21.5mm, diameter6.3mm).<br/>Long Spray Jet (Length 33.5mm, diameter 6.3mm).<br/>Oversize Short Spray Jet (length 21.5mm, diameter6.7mm).<br/>Oversize Long Spray Jet (Length 33.5mm, diameter 6.7mm).

Literature: 993 Workshop Manual, Volume 1, Group 13.

Important Notice: Porsche Cars N.A Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers. ©1997 Porsche Cars North America, Inc.

Dealership Distribution Routing	Service Manager Asst. Manager		Shop Foreman Warranty Admin.		Service Technician Service Technician					
The trademarks $Porsche^{\mathbb{R}}$ , Targa $^{\mathbb{R}}$ , Car	rera®, Boxster®,Tiptro	nic <sup>®</sup> , Varioram <sup>®</sup>	and the Porsche Cres	st are registered t	rademarks of Dr. Ing. h.c.F	. Porsche AG	and its affiliate	e, Porsche Cars	s North America	, Inc.
Date: 9-30-97 Page 2 of 2			Se	rvice			©1997 Por	sche Cars N	orth America	, Inc.